

Maintenance- Record of Thorough Examination - Lifting Equipment LWC-20-01 V6

29 Apr 2026 / Chains / 379 00.5Q3C-379 3.15 Ton 1 Leg 10mm
Chain Bog Mat 5 / Bm5

Complete

Score	12 / 12 (100%)	Flagged items	0	Actions	0
Site conducted	L&W House, Stane Street, Billingshurst RH14 9AE, UK				
Conducted on	29 Apr 2026 12:50 PM BST				
Type of equipment	Chains				
what chains are you inspecting	379 00.5Q3C-379 3.15 Ton 1 Leg 10mm Chain Bog Mat 5				
What Fleet number of the Machine / attachment is the chain on	Bm5				
Prepared by	Darren Gomm				
Document number	005120				

Inspection		10 / 10 (100%)
What are you inspecting	Chains	
what chains are you inspecting	379 00.5Q3C-379 3.15 Ton 1 Leg 10mm Chain Bog Mat 5	
What Fleet number of the Machine / attachment is the chain on	Bm5	
Date of last examination	not known	
are there any signs of defects/ cracks etc	No	
Is the SWL clearly identified	Yes	
is the equipment safe to use	Yes	
Details of defects found	No Defects Identified	
Latest date by which next thorough examination must be carried out	28 Oct 2026	
Name of the person Responsible for the examination	Darren Gomm	
is this equipment safe to use	Yes	

DECLARATION:

I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and was found free from any defects likely to affect safety other than those listed above on (date) and that the above particulars are correct.

Signature



D.gomm
29 Apr 2026 12:51 PM BST