

Maintenance- Record of Thorough Examination - Lifting Equipment LWC-20-01 V6

30 Apr 2026 / Chains / 385 00.5Q3I-385 3.15 Ton 1 Leg 10mm
Chain Bog Mat 2 / Bog mat 2

Complete


Score	12 / 12 (100%)	Flagged items	0	Actions	0
Site conducted	2 Kernel Court Guildford England GU1 4UD United Kingdom (51.24224111047766, -0.5824696845009519)				
Conducted on	30 Apr 2026 11:05 AM BST				
Type of equipment	Chains				
what chains are you inspecting	385 00.5Q3I-385 3.15 Ton 1 Leg 10mm Chain Bog Mat 2				
What Fleet number of the Machine / attachment is the chain on	Bog mat 2				
Prepared by	Ed Staveley -				
Document number	005145				

Inspection		10 / 10 (100%)
What are you inspecting	Chains	
what chains are you inspecting	385 00.5Q3I-385 3.15 Ton 1 Leg 10mm Chain Bog Mat 2	
What Fleet number of the Machine / attachment is the chain on	Bog mat 2	
Date of last examination	not known	
are there any signs of defects/ cracks etc	No	
Is the SWL clearly identified	Yes	
is the equipment safe to use	Yes	
Details of defects found	No Defects Identified	
Latest date by which next thorough examination must be carried out	29 Oct 2026	
Name of the person Responsible for the examination	Ed Staveley -	
is this equipment safe to use	Yes	

DECLARATION:

I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and was found free from any defects likely to affect safety other than those listed above on (date) and that the above particulars are correct.

Signature



E Staveley
30 Apr 2026 11:06 AM BST