

Maintenance- Record of Thorough Examination - Lifting Equipment LWC-20-01 V6

30 Apr 2026 / Chains / 403 00.5Q3A3-403 3.15 Ton 1 Leg 10mm
Chain Bog Mat 28 / Bog mat 28

Complete


Score	12 / 12 (100%)	Flagged items	0	Actions	0
Site conducted	58 Hare Lane Esher England KT10 0QU United Kingdom (51.36276283412362, -0.3483094046491741)				
Conducted on	30 Apr 2026 3:02 PM BST				
Type of equipment	Chains				
what chains are you inspecting	403 00.5Q3A3-403 3.15 Ton 1 Leg 10mm Chain Bog Mat 28				
What Fleet number of the Machine / attachment is the chain on	Bog mat 28				
Prepared by	Ed Staveley -				
Document number	005159				

Inspection		10 / 10 (100%)
What are you inspecting	Chains	
what chains are you inspecting	403 00.5Q3A3-403 3.15 Ton 1 Leg 10mm Chain Bog Mat 28	
What Fleet number of the Machine / attachment is the chain on	Bog mat 28	
Date of last examination	not known	
are there any signs of defects/ cracks etc	No	
Is the SWL clearly identified	Yes	
is the equipment safe to use	Yes	
Details of defects found	No Defects Identified	
Latest date by which next thorough examination must be carried out	29 Oct 2026	
Name of the person Responsible for the examination	Ed Staveley -	
is this equipment safe to use	Yes	

DECLARATION:

I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and was found free from any defects likely to affect safety other than those listed above on (date) and that the above particulars are correct.

Signature



E Staveley
30 Apr 2026 3:03 PM BST