

## Maintenance- Record of Thorough Examination - Lifting Equipment LWC-20-01 V6

30 Apr 2026 / Chains / 405 00.5Q3A5-405 3.15 Ton 1 Leg 10mm  
Chain Bog Mat 29 / Bog Mat 29

Complete

|                                                               |                                                                                                                   |               |   |         |   |
|---------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------|---------------|---|---------|---|
| Score                                                         | 12 / 12 (100%)                                                                                                    | Flagged items | 0 | Actions | 0 |
| Site conducted                                                | Tisserand Farm<br>Billingshurst England RH14 9AE<br>United Kingdom<br>(51.03900688449721,<br>-0.4400494434734829) |               |   |         |   |
| Conducted on                                                  | 30 Apr 2026 7:57 AM BST                                                                                           |               |   |         |   |
| Type of equipment                                             | Chains                                                                                                            |               |   |         |   |
| what chains are you inspecting                                | 405 00.5Q3A5-405 3.15 Ton 1 Leg<br>10mm Chain Bog Mat 29                                                          |               |   |         |   |
| What Fleet number of the Machine / attachment is the chain on | Bog Mat 29                                                                                                        |               |   |         |   |
| Prepared by                                                   | Harry Poulton -                                                                                                   |               |   |         |   |
| Document number                                               | 005135                                                                                                            |               |   |         |   |

|                                                                    |                                                          |                |
|--------------------------------------------------------------------|----------------------------------------------------------|----------------|
| Inspection                                                         |                                                          | 10 / 10 (100%) |
| What are you inspecting                                            | Chains                                                   |                |
| what chains are you inspecting                                     | 405 00.5Q3A5-405 3.15 Ton 1 Leg<br>10mm Chain Bog Mat 29 |                |
| What Fleet number of the Machine / attachment is the chain on      | Bog Mat 29                                               |                |
| Date of last examination                                           | not known                                                |                |
| are there any signs of defects/ cracks etc                         | No                                                       |                |
| Is the SWL clearly identified                                      | Yes                                                      |                |
| is the equipment safe to use                                       | Yes                                                      |                |
| Details of defects found                                           | No Defects Identified                                    |                |
| Latest date by which next thorough examination must be carried out | 29 Oct 2026                                              |                |
| Name of the person Responsible for the examination                 | Harry Poulton -                                          |                |
| is this equipment safe to use                                      | Yes                                                      |                |

DECLARATION:

I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and was found free from any defects likely to affect safety other than those listed above on (date) and that the above particulars are correct.

Signature



Harry Poulton  
30 Apr 2026 7:59 AM BST