

Maintenance- Record of Thorough Examination - Lifting Equipment LWC-20-01 V6

30 Apr 2026 / Chains / 418 00.5Q3A18-418 3.15 Ton 1 Leg
10mm Chain Bog Mat 22 / BM22

Complete

Score	12 / 12 (100%)	Flagged items	0	Actions	0
Site conducted	168 Damsel House Croydon England CR0 6BZ United Kingdom (51.38613055547648, -0.08665242780549344)				
Conducted on	30 Apr 2026 12:08 PM BST				
Type of equipment	Chains				
what chains are you inspecting	418 00.5Q3A18-418 3.15 Ton 1 Leg 10mm Chain Bog Mat 22				
What Fleet number of the Machine / attachment is the chain on	BM22				
Prepared by	Marvelous Kamusoko -				
Document number	005153				

Inspection		10 / 10 (100%)
What are you inspecting	Chains	
what chains are you inspecting	418 00.5Q3A18-418 3.15 Ton 1 Leg 10mm Chain Bog Mat 22	
What Fleet number of the Machine / attachment is the chain on	BM22	
Date of last examination	known date	
last known date	7 Nov 2025	
are there any signs of defects/ cracks etc	No	
Is the SWL clearly identified	Yes	
is the equipment safe to use	Yes	
Details of defects found	No Defects Identified	
Latest date by which next thorough examination must be carried out	29 Oct 2026	
Name of the person Responsible for the examination	Marvelous Kamusoko -	
is this equipment safe to use	Yes	

DECLARATION:

I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and was found free from any defects likely to affect safety other than those listed above on (date) and that the above particulars are correct.

Signature



Marv Kamusoko
30 Apr 2026 12:10 PM BST