

Maintenance- Record of Thorough Examination - Lifting Equipment LWC-20-01 V6

30 Apr 2026 / Chains / 420 00.5Q3A20-420 3.15 Ton 1 Leg
10mm Chain Bog Mat 27 / Bog mat 27

Complete

Score	12 / 12 (100%)	Flagged items	0	Actions	0
Site conducted	Arundel England BN18 United Kingdom (50.81173040431287, -0.6028071140818647)				
Conducted on	30 Apr 2026 6:11 PM BST				
Type of equipment	Chains				
what chains are you inspecting	420 00.5Q3A20-420 3.15 Ton 1 Leg 10mm Chain Bog Mat 27				
What Fleet number of the Machine / attachment is the chain on	Bog mat 27				
Prepared by	Charlie Young				
Document number	005162				

Inspection		10 / 10 (100%)
What are you inspecting	Chains	
what chains are you inspecting	420 00.5Q3A20-420 3.15 Ton 1 Leg 10mm Chain Bog Mat 27	
What Fleet number of the Machine / attachment is the chain on	Bog mat 27	
Date of last examination	not known	
are there any signs of defects/ cracks etc	No	
Is the SWL clearly identified	Yes	
is the equipment safe to use	Yes	
Details of defects found	No Defects Identified	
Latest date by which next thorough examination must be carried out	29 Oct 2026	
Name of the person Responsible for the examination	Charlie Young	
is this equipment safe to use	Yes	

DECLARATION:

I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and was found free from any defects likely to affect safety other than those listed above on (date) and that the above particulars are correct.

Signature



Charlie young
30 Apr 2026 6:14 PM BST