

## Maintenance- Record of Thorough Examination - Lifting Equipment LWC-20-01 V6

30 Apr 2026 / Chains / 429 00.5Q3A29-429 3.15 Ton 1 Leg  
10mm Chain Bog Mat 20 / BM20

Complete

|                                                               |                                                                                                    |               |   |         |   |
|---------------------------------------------------------------|----------------------------------------------------------------------------------------------------|---------------|---|---------|---|
| Score                                                         | 12 / 12 (100%)                                                                                     | Flagged items | 0 | Actions | 0 |
| Site conducted                                                | Tait Road<br>Croydon England CR0<br>United Kingdom<br>(51.38635386712337,<br>-0.08729741505412407) |               |   |         |   |
| Conducted on                                                  | 30 Apr 2026 12:04 PM BST                                                                           |               |   |         |   |
| Type of equipment                                             | Chains                                                                                             |               |   |         |   |
| what chains are you inspecting                                | 429 00.5Q3A29-429 3.15 Ton 1<br>Leg 10mm Chain Bog Mat 20                                          |               |   |         |   |
| What Fleet number of the Machine / attachment is the chain on | BM20                                                                                               |               |   |         |   |
| Prepared by                                                   | Marvelous Kamusoko -                                                                               |               |   |         |   |
| Document number                                               | 005151                                                                                             |               |   |         |   |

|                                                                    |                                                           |                |
|--------------------------------------------------------------------|-----------------------------------------------------------|----------------|
| Inspection                                                         |                                                           | 10 / 10 (100%) |
| What are you inspecting                                            | Chains                                                    |                |
| what chains are you inspecting                                     | 429 00.5Q3A29-429 3.15 Ton 1<br>Leg 10mm Chain Bog Mat 20 |                |
| What Fleet number of the Machine / attachment is the chain on      | BM20                                                      |                |
| Date of last examination                                           | known date                                                |                |
| last known date                                                    | 7 Nov 2025                                                |                |
| are there any signs of defects/ cracks etc                         | No                                                        |                |
| Is the SWL clearly identified                                      | Yes                                                       |                |
| is the equipment safe to use                                       | Yes                                                       |                |
| Details of defects found                                           | No Defects Identified                                     |                |
| Latest date by which next thorough examination must be carried out | 29 Oct 2026                                               |                |
| Name of the person Responsible for the examination                 | Marvelous Kamusoko -                                      |                |
| is this equipment safe to use                                      | Yes                                                       |                |

DECLARATION:

I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and was found free from any defects likely to affect safety other than those listed above on (date) and that the above particulars are correct.

Signature



Marv Kamusoko  
30 Apr 2026 12:06 PM BST