



Maintenance- Record of Thorough Examination - Lifting Equipment LWC-20-01 V6

4 Nov 2025 / Chains / 381 00.5Q3E-381 3.15 Ton 1 Leg 10mm
Chain Bog Mat 6 / Bogmat 6

Complete

Score	14 / 14 (100%)	Flagged items	0	Actions	0
Site conducted	9 Dominion Road Croydon England CR0 6JP United Kingdom (51.38591024675204, -0.0813663457114773)				
Conducted on	4 Nov 2025 12:56 PM GMT				
Type of equipment	Chains				
what chains are you inspecting	381 00.5Q3E-381 3.15 Ton 1 Leg 10mm Chain Bog Mat 6				
What Fleet number of the Machine / attachment is the chain on	Bogmat 6				
Prepared by	Marvelous Kamusoko -				
Document number	004315				

Inspection	12 / 12 (100%)
What are you inspecting	Chains
what chains are you inspecting	381 00.5Q3E-381 3.15 Ton 1 Leg 10mm Chain Bog Mat 6
What Fleet number of the Machine / attachment is the chain on	Bogmat 6
Date of last examination	known date
last known date	25 Feb 2025
are there any signs of defects/ cracks etc	No
are all of the catch's fully functioning	Yes
Is the SWL clearly identified	Yes
is the equipment safe to use	Yes
Details of defects found	No Defects Identified
What parts if any where inaccessible (to be completed only after examination of a hoist or lift)	NA
Latest date by which next thorough examination must be carried out	3 May 2026
Name of the person Responsible for the examination	Marvelous Kamusoko -
is this equipment safe to use	Yes

DECLARATION:

I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and was found free from any defects likely to affect safety other than those listed above on (date) and that the above particulars are correct.

Signature



Marv Kamusoko
4 Nov 2025 12:58 PM GMT