



## Maintenance- Record of Thorough Examination - Lifting Equipment LWC-20-01 V6

4 Nov 2025 / Chains / 382 00.5Q3F-382 3.15 Ton 1 Leg 10mm  
Chain Bog Mat 6 / Bogmat 6

Complete

Score	14 / 14 (100%)	Flagged items	0	Actions	0
Site conducted	Tait Road Croydon England CR0 United Kingdom (51.386404742381664, -0.08671365527941347)				
Conducted on	4 Nov 2025 12:14 PM GMT				
Type of equipment	Chains				
what chains are you inspecting	382 00.5Q3F-382 3.15 Ton 1 Leg 10mm Chain Bog Mat 6				
What Fleet number of the Machine / attachment is the chain on	Bogmat 6				
Prepared by	Marvelous Kamusoko -				
Document number	004314				

<b>Inspection</b>	12 / 12 (100%)
<b>What are you inspecting</b>	Chains
<b>what chains are you inspecting</b>	382 00.5Q3F-382 3.15 Ton 1 Leg 10mm Chain Bog Mat 6
<b>What Fleet number of the Machine / attachment is the chain on</b>	Bogmat 6
<b>Date of last examination</b>	known date
<b>last known date</b>	25 Feb 2025
<b>are there any signs of defects/ cracks etc</b>	No
<b>are all of the catch's fully functioning</b>	Yes
<b>Is the SWL clearly identified</b>	Yes
<b>is the equipment safe to use</b>	Yes
<b>Details of defects found</b>	No Defects Identified
<b>What parts if any where inaccessible (to be completed only after examination of a hoist or lift)</b>	NA
<b>Latest date by which next thorough examination must be carried out</b>	3 May 2026
<b>Name of the person Responsible for the examination</b>	Marvelous Kamusoko -
<b>is this equipment safe to use</b>	Yes

**DECLARATION:**

I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and was found free from any defects likely to affect safety other than those listed above on (date) and that the above particulars are correct.

**Signature**



Marv Kamusoko  
4 Nov 2025 12:33 PM GMT