



## Maintenance- Record of Thorough Examination - Lifting Equipment LWC-20-01 V6

5 Nov 2025 / Chains / 383 00.5Q3G-383 3.15 Ton 1 Leg 10mm  
Chain Bog Mat 9 / BM09

Complete


Score	14 / 14 (100%)	Flagged items	0	Actions	0
Site conducted	39-44 Churchfields Road Salisbury England SP2 United Kingdom (51.07060414521313, -1.8102287146981175)				
Conducted on	5 Nov 2025 2:39 PM GMT				
Type of equipment	Chains				
what chains are you inspecting	383 00.5Q3G-383 3.15 Ton 1 Leg 10mm Chain Bog Mat 9				
What Fleet number of the Machine / attachment is the chain on	BM09				
Prepared by	Del Taylor				
Document number	004353				

<b>Inspection</b>	12 / 12 (100%)
<b>What are you inspecting</b>	Chains
<b>what chains are you inspecting</b>	383 00.5Q3G-383 3.15 Ton 1 Leg 10mm Chain Bog Mat 9
<b>What Fleet number of the Machine / attachment is the chain on</b>	BM09
<b>Date of last examination</b>	known date
<b>last known date</b>	2 Mar 2025
<b>are there any signs of defects/ cracks etc</b>	No
<b>are all of the catch's fully functioning</b>	Yes
<b>Is the SWL clearly identified</b>	Yes
<b>is the equipment safe to use</b>	Yes
<b>Details of defects found</b>	No Defects Identified
<b>What parts if any where inaccessible (to be completed only after examination of a hoist or lift)</b>	NA
<b>Latest date by which next thorough examination must be carried out</b>	4 May 2026
<b>Name of the person Responsible for the examination</b>	Del Taylor
<b>is this equipment safe to use</b>	Yes

**DECLARATION:**

I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and was found free from any defects likely to affect safety other than those listed above on (date) and that the above particulars are correct.

**Signature**



D Taylor  
5 Nov 2025 2:42 PM GMT