



Maintenance- Record of Thorough Examination - Lifting Equipment LWC-20-01 V6

5 Nov 2025 / Chains / 399 00.5Q3W-399 3.15 Ton1 Leg 10mm Chain Bog Mat 12 / Bogmat 12

Complete

| | | | | | |
|--------------|----------------|----------------------|---|----------------|---|
| Score | 14 / 14 (100%) | Flagged items | 0 | Actions | 0 |
|--------------|----------------|----------------------|---|----------------|---|

Site conducted

Brook Hill, Albury
Guildford
England
GU5
United Kingdom
(51.20798122905735,
-0.4827246214334864)

Conducted on

5 Nov 2025 8:15 AM GMT

Type of equipment

Chains

what chains are you inspecting

399 00.5Q3W-399 3.15 Ton1 Leg
10mm Chain Bog Mat 12

What Fleet number of the Machine / attachment is the chain on

Bogmat 12

Prepared by

Marvelous Kamusoko -

Document number

004332

| | |
|---|--|
| Inspection | 12 / 12 (100%) |
| What are you inspecting | Chains |
| what chains are you inspecting | 399 00.5Q3W-399 3.15 Ton1 Leg 10mm Chain Bog Mat 12 |
| What Fleet number of the Machine / attachment is the chain on | Bogmat 12 |
| Date of last examination | known date |
| last known date | 5 Feb 2025 |
| are there any signs of defects/ cracks etc | No |
| are all of the catch's fully functioning | Yes |
| Is the SWL clearly identified | Yes |
| is the equipment safe to use | Yes |
| Details of defects found | No Defects Identified |
| What parts if any where inaccessible (to be completed only after examination of a hoist or lift) | NA |
| Latest date by which next thorough examination must be carried out | 4 May 2026 |
| Name of the person Responsible for the examination | Marvelous Kamusoko - |
| is this equipment safe to use | Yes |

DECLARATION:

I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and was found free from any defects likely to affect safety other than those listed above on (date) and that the above particulars are correct.

Signature



Marv Kamusoko
5 Nov 2025 8:21 AM GMT