



Maintenance- Record of Thorough Examination - Lifting Equipment LWC-20-01 V6

5 Nov 2025 / Chains / 401 00.5Q3A1-401 3.15 Ton 1 Leg 10mm
Chain Bog Mat 30 / BM30

Complete


Score	14 / 14 (100%)	Flagged items	0	Actions	0
Site conducted	39-44 Churchfields Road Salisbury England SP2 United Kingdom (51.07060967557675, -1.810257703655336)				
Conducted on	5 Nov 2025 3:04 PM GMT				
Type of equipment	Chains				
what chains are you inspecting	401 00.5Q3A1-401 3.15 Ton 1 Leg 10mm Chain Bog Mat 30				
What Fleet number of the Machine / attachment is the chain on	BM30				
Prepared by	Del Taylor				
Document number	004364				

Inspection	12 / 12 (100%)
What are you inspecting	Chains
what chains are you inspecting	401 00.5Q3A1-401 3.15 Ton 1 Leg 10mm Chain Bog Mat 30
What Fleet number of the Machine / attachment is the chain on	BM30
Date of last examination	known date
last known date	2 Mar 2025
are there any signs of defects/ cracks etc	No
are all of the catch's fully functioning	Yes
Is the SWL clearly identified	Yes
is the equipment safe to use	Yes
Details of defects found	No Defects Identified
What parts if any where inaccessible (to be completed only after examination of a hoist or lift)	NA
Latest date by which next thorough examination must be carried out	4 May 2026
Name of the person Responsible for the examination	Del Taylor
is this equipment safe to use	Yes

DECLARATION:

I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and was found free from any defects likely to affect safety other than those listed above on (date) and that the above particulars are correct.

Signature



D Taylor
5 Nov 2025 3:07 PM GMT