



# Maintenance- Record of Thorough Examination - Lifting Equipment LWC-20-01 V6

5 Nov 2025 / Chains / 433 00.5Q3A33-433 3.15 Ton 1 Leg  
10mm Chain Bog Mat 15 / Bogmat 15

Complete

<b>Score</b>	14 / 14 (100%)	<b>Flagged items</b>	0	<b>Actions</b>	0
<b>Site conducted</b>	17 Bede House, Saxon Close Surbiton England KT6 6BP United Kingdom (51.391348758822, -0.3045416062604936)				
<b>Conducted on</b>	5 Nov 2025 2:17 PM GMT				
<b>Type of equipment</b>	Chains				
<b>what chains are you inspecting</b>	433 00.5Q3A33-433 3.15 Ton 1 Leg 10mm Chain Bog Mat 15				
<b>What Fleet number of the Machine / attachment is the chain on</b>	Bogmat 15				
<b>Prepared by</b>	Marvelous Kamusoko -				
<b>Document number</b>	004347				

<b>Inspection</b>	12 / 12 (100%)
<b>What are you inspecting</b>	Chains
<b>what chains are you inspecting</b>	433 00.5Q3A33-433 3.15 Ton 1 Leg 10mm Chain Bog Mat 15
<b>What Fleet number of the Machine / attachment is the chain on</b>	Bogmat 15
<b>Date of last examination</b>	known date
<b>last known date</b>	25 Feb 2025
<b>are there any signs of defects/ cracks etc</b>	No
<b>are all of the catch's fully functioning</b>	Yes
<b>Is the SWL clearly identified</b>	Yes
<b>is the equipment safe to use</b>	Yes
<b>Details of defects found</b>	No Defects Identified
<b>What parts if any where inaccessible (to be completed only after examination of a hoist or lift)</b>	NA
<b>Latest date by which next thorough examination must be carried out</b>	4 May 2026
<b>Name of the person Responsible for the examination</b>	Marvelous Kamusoko -
<b>is this equipment safe to use</b>	Yes

**DECLARATION:**

I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and was found free from any defects likely to affect safety other than those listed above on (date) and that the above particulars are correct.

**Signature**



Marv Kamusoko  
5 Nov 2025 2:19 PM GMT