



Maintenance- Record of Thorough Examination - Lifting Equipment LWC-20-01 V6

6 Nov 2025 / Chains / 408 00.5Q3A8-408 3.15 Ton 1 Leg 10mm
Chain Bog Mat 23 / Bm23

Complete

Score	14 / 14 (100%)	Flagged items	0	Actions	0
Site conducted	L&W House, Stane Street, Billingshurst RH14 9AE, UK (51.0390667, -0.4402337)				
Conducted on	6 Nov 2025 2:29 PM GMT				
Type of equipment	Chains				
what chains are you inspecting	408 00.5Q3A8-408 3.15 Ton 1 Leg 10mm Chain Bog Mat 23				
What Fleet number of the Machine / attachment is the chain on	Bm23				
Prepared by	Darren Gomm				
Document number	004382				

Inspection		12 / 12 (100%)
What are you inspecting	Chains	
what chains are you inspecting	408 00.5Q3A8-408 3.15 Ton 1 Leg 10mm Chain Bog Mat 23	
What Fleet number of the Machine / attachment is the chain on	Bm23	
Date of last examination	not known	
are there any signs of defects/ cracks etc	No	
are all of the catch's fully functioning	Yes	
Is the SWL clearly identified	Yes	
is the equipment safe to use	Yes	
Details of defects found	No Defects Identified	
What parts if any where inaccessible (to be completed only after examination of a hoist or lift)	NA	
Latest date by which next thorough examination must be carried out	5 May 2026	
Name of the person Responsible for the examination	Darren Gomm	
is this equipment safe to use	Yes	

DECLARATION:

I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and was found free from any defects likely to affect safety other than those listed above on (date) and that the above particulars are correct.

Signature



D.gomm
6 Nov 2025 2:30 PM GMT