



Maintenance- Record of Thorough Examination - Lifting Equipment LWC-20-01 V6

7 Nov 2025 / Chains / 409 00.5Q3A9-409 3.15 Ton 1 Leg 10mm Chain Bog Mat 21 / BM21

Complete

Score	14 / 14 (100%)	Flagged items	0	Actions	0
Site conducted					Yard
Conducted on					7 Nov 2025 8:40 AM GMT
Type of equipment					Chains
what chains are you inspecting					409 00.5Q3A9-409 3.15 Ton 1 Leg 10mm Chain Bog Mat 21
What Fleet number of the Machine / attachment is the chain on					BM21
Prepared by					John Stevens -
Document number					004400

Inspection	12 / 12 (100%)
What are you inspecting	Chains
what chains are you inspecting	409 00.5Q3A9-409 3.15 Ton 1 Leg 10mm Chain Bog Mat 21
What Fleet number of the Machine / attachment is the chain on	BM21
Date of last examination	not known
are there any signs of defects/ cracks etc	No
are all of the catch's fully functioning	Yes
Is the SWL clearly identified	Yes
is the equipment safe to use	Yes
Details of defects found	No Defects Identified
What parts if any where inaccessible (to be completed only after examination of a hoist or lift)	NA
Latest date by which next thorough examination must be carried out	6 May 2026
Name of the person Responsible for the examination	John Stevens -
is this equipment safe to use	Yes

DECLARATION:

I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and was found free from any defects likely to affect safety other than those listed above on (date) and that the above particulars are correct.

Signature



Jstevens
7 Nov 2025 8:42 AM GMT