



Maintenance- Record of Thorough Examination - Lifting Equipment LWC-20-01 V6

7 Nov 2025 / Chains / 418 00.5Q3A18-418 3.15 Ton 1 Leg
10mm Chain Bog Mat 22 / BM22

Complete

Score	14 / 14 (100%)	Flagged items	0	Actions	0
Site conducted	Lw yard				
Conducted on	7 Nov 2025 8:21 AM GMT				
Type of equipment	Chains				
what chains are you inspecting	418 00.5Q3A18-418 3.15 Ton 1 Leg 10mm Chain Bog Mat 22				
What Fleet number of the Machine / attachment is the chain on	BM22				
Prepared by	John Stevens -				
Document number	004398				

Inspection		12 / 12 (100%)
What are you inspecting	Chains	
what chains are you inspecting	418 00.5Q3A18-418 3.15 Ton 1 Leg 10mm Chain Bog Mat 22	
What Fleet number of the Machine / attachment is the chain on	BM22	
Date of last examination	not known	
are there any signs of defects/ cracks etc	No	
are all of the catch's fully functioning	Yes	
Is the SWL clearly identified	Yes	
is the equipment safe to use	Yes	
Details of defects found	No Defects Identified	
What parts if any where inaccessible (to be completed only after examination of a hoist or lift)	NA	
Latest date by which next thorough examination must be carried out	6 May 2026	
Name of the person Responsible for the examination	John Stevens -	
is this equipment safe to use	Yes	

DECLARATION:

I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and was found free from any defects likely to affect safety other than those listed above on (date) and that the above particulars are correct.

Signature



Jstevens
7 Nov 2025 8:23 AM GMT