



Maintenance- Record of Thorough Examination - Lifting Equipment LWC-20-01 V6

7 Nov 2025 / Chains / 429 00.5Q3A29-429 3.15 Ton 1 Leg
10mm Chain Bog Mat 20 / Bm20

Complete

Score	14 / 14 (100%)	Flagged items	0	Actions	0
Site conducted	Tisserand Farm, Stane Street Billingshurst England RH14 9AE United Kingdom (51.03905880828485, -0.43986274860840274)				
Conducted on	7 Nov 2025 8:16 AM GMT				
Type of equipment	Chains				
what chains are you inspecting	429 00.5Q3A29-429 3.15 Ton 1 Leg 10mm Chain Bog Mat 20				
What Fleet number of the Machine / attachment is the chain on	Bm20				
Prepared by	Charlie Young				
Document number	004397				

Inspection	12 / 12 (100%)
What are you inspecting	Chains
what chains are you inspecting	429 00.5Q3A29-429 3.15 Ton 1 Leg 10mm Chain Bog Mat 20
What Fleet number of the Machine / attachment is the chain on	Bm20
Date of last examination	not known
are there any signs of defects/ cracks etc	No
are all of the catch's fully functioning	Yes
Is the SWL clearly identified	Yes
is the equipment safe to use	Yes
Details of defects found	No Defects Identified
What parts if any where inaccessible (to be completed only after examination of a hoist or lift)	NA
Latest date by which next thorough examination must be carried out	6 May 2026
Name of the person Responsible for the examination	Charlie Young
is this equipment safe to use	Yes

DECLARATION:

I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and was found free from any defects likely to affect safety other than those listed above on (date) and that the above particulars are correct.

Signature



Charlie young
7 Nov 2025 8:17 AM GMT