



CONTRACTORS LTD

Maintenance- Record of Thorough Examination - Lifting Equipment LWC-20-01 V6

30 Apr 2026 / Chains / 397 00.5Q3U-397 3.15 Ton 1 Leg 10mm Chain Bog Mat 1 / Bog mat 1

Complete


Score	12 / 12 (100%)	Flagged items	0	Actions	0
Site conducted	King Edwards Court Guildford England GU1 4LG United Kingdom (51.24190099854922, -0.5822930302748891)				
Conducted on	30 Apr 2026 11:11 AM BST				
Type of equipment	Chains				
what chains are you inspecting	397 00.5Q3U-397 3.15 Ton 1 Leg 10mm Chain Bog Mat 1				
What Fleet number of the Machine / attachment is the chain on	Bog mat 1				
Prepared by	Ed Staveley -				
Document number	005147				

Inspection	10 / 10 (100%)
What are you inspecting	Chains
what chains are you inspecting	397 00.5Q3U-397 3.15 Ton 1 Leg 10mm Chain Bog Mat 1
What Fleet number of the Machine / attachment is the chain on	Bog mat 1
Date of last examination	not known
are there any signs of defects/ cracks etc	No
Is the SWL clearly identified	Yes
is the equipment safe to use	Yes
Details of defects found	No Defects Identified
Latest date by which next thorough examination must be carried out	29 Oct 2026
Name of the person Responsible for the examination	Ed Staveley -
is this equipment safe to use	Yes

DECLARATION:

I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and was found free from any defects likely to affect safety other than those listed above on (date) and that the above particulars are correct.

Signature



E Staveley
30 Apr 2026 11:12 AM BST